


Hogeweg 21 6367 BA Voerendaal The Netherlands

1 : +31-(0)45 574 81 91

: www.A1TouchSolution.nl

Assemble User Manual



Accessory list (as below pic):

X axis transmitting tub : 1 PCS
Y axis transmitting tub : 1 PCS
Y axis receiving tube : 1 PCS
X axis receiving tube : 1 PCS


5. Screws (KM2.5×4mm) ∶ 14Pcs (2pcs backup)



Step 1:

Match the NO. on the touch frame (No. A match No.A, No.B match No.B, No.C match No.C ,No.D match No.D) Same in case of numbers..












Step2:Open the cover of each corner (as below)





Step 3:Connect the spare of the 10 pins connector and fix the cover of the corner and tighten screws.





Step 4:

According to the same principle, repeat the corner B,C,D and finish the assembling as below:



ATTENTION:

1. Open cover of corner before connecting/disconnecting frame to avoid broken 10 pins connector!



- 2. Make sure unit is assembled with corners on **90 degrees and in one surface** to be sure of optimal receiving of transmitted signal.
- 3. First test the assembled unit on a flat surface or on top of monitor/tv before fixed mounting with tape !!
- 4. Assemble the unit with adhesive to to front of display with cable outlet on bottom side!